
UNDERGROUND AND SAMPLE MAP
Attached to Geological Map and report on
THE OYLER LODE
MARIPOSA CO., CALIF.
BY PHIL. B. DOLMAN, GEOLOGIST.
OCT 1934.
LEGEND
Greenstone & Tuff.
Vein filling - Quartz
General sample from cars.
Trench sample across vein.
Trench sample across vein.
Assay values Gold at $35.00 per oz
Collar
Crossing
Old Stope
Bottom of Old Shaft
Horizontal Section - Drift at 100 Ft. Level
Horizontal Section - Drift at 175 Ft. Level.
Strike - S 30°E.
Strike - S 60°E.
Strike - S 70°E.
Water Level
Vein Strike S 30°E.
Grade - 1.5 Ft. in 100.
Axis Syn
Axis Ant
Trend of Pinch
Sump
W. L.
(Continued below)
50 Ft.
100 Ft.
150 Ft.
175 Ft.
200 Ft.
250 Ft.
300 Ft.
135 Ft.